



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining


MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

October 1, 2012

Reviewed: 

**Mine Name:** Torrey Quarry  
**Operator Name:** Star Stone Quarries

**Permit number:** M/055/0016  
**Inspection Date:** August 28,  
2012  
**Time:** About 5:00-5:20 PM

**Inspector(s):** Paul Baker  
**Other Participants:** None  
**Mine Status:** Active

**Weather:** Cloudy, 70s

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds, Permit Fees	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**  
This was a routine inspection.

#### Inspection Summary:

1. Permits, Revisions, Transfer, Bonds, Permit Fees  
The permit fee is up to date. The Division holds a surety bond in the amount of \$40,000, and it is due for re-evaluation on August 24, 2016.

The operator still owes \$528.00 for notice of violation MN-2008-41-03.

#### 3. Protection of Drainages / Erosion Control

There had obviously been a substantial rain storm, and about half of the check dam has washed away. It needs to be re-built.

#### Conclusions and Recommendations:

The check dam needs to be re-built. This needs to be done before the next inspection.

The operator needs to pay the fine for notice of violation MN-2008-41-03.

Inspection Date: August 28, 2012; Report Date: October 1, 2012

Page 2 of 2

M/055/0016

Inspector's Signature

JRB

Directions:

PBB

cc: Star Stone

JReay@blm.gov

O:\M055-Wayne\M0550016-Torrey\_Quarry\inspections\ins-08282012.doc



Photo 1.



Photo 3. This and Photo 4 are overviews of part of the area being mined.



Photo 2. The portion of the check dam that was washed out is in the left center portion of this picture.



Photo 4.